

TABLE OF CONTENTS

	<u>Page</u>
TABLE OF CONTENTS	i
1. INTRODUCTION	1
2. STUDY AREA	2
3. GEOMORPHIC ASSESSMENT	4
3.1. LEVEL I – GEOMORPHIC CHARACTERIZATION	4
3.1.1. Lower South Fork Coquille River	6
3.1.2. Streams in the Dement, Yellow, and Hayes Creek Watersheds	8
3.2. LEVEL II – MORPHOLOGICAL DESCRIPTIONS	8
3.2.1. Extensive Survey of the Lower South Fork	9
3.2.2. Representative Channel Segments	11
3.3. LEVEL III – ASSESSMENT OF STREAM CONDITION AND DEPARTURE	13
3.3.1. Existing River Conditions	14
3.3.2. Departure from Potential River Conditions	18
3.3.3. Implications for Restoring Channel Stability	30
4. SHADOW MODELING	32
4.1. DATA ACQUIRED FOR EVALUATIONS OF STREAM SHADING	32
4.1.1. SHADOW Inputs	34
4.1.2. Other Shade-related Parameters in the Database	42
4.2. MODEL CALIBRATION	43
4.3. MODELING SCENARIOS	45
4.3.1. Assessment of Existing and Potential Levels of Stream Shade	45
4.3.2. Assumptions Made When Modeling Potential Shade	45
4.4. MODEL OUTPUT	48
5. RESTORATION OPPORTUNITIES AND PRIORITIES	54
5.1. RIPARIAN RESTORATION ALONG THE LOWER STUDY REACHES	55
5.1.1. Potential Priority Areas for Early Action Along the Lower South Fork	56
6. REFERENCES	57
APPENDIX A – Rosgen Level I Channel Types and Related Data	
APPENDIX B – Photos of the Study Area	
APPENDIX C – Extensive Survey Data	
APPENDIX D – Channel Cross-Sections	
APPENDIX E – Wolman Pebble Counts	
APPENDIX F – PWA Technical Memorandum	
APPENDIX G – Bankfull Channel Characteristics for Channel Cross-Sections	
APPENDIX H – Assorted Level III Information	
APPENDIX I – Interpretations of 1939 and 1997 Air Photos	
APPENDIX J – SHADOW Data and Output	